

Cartelli della raccolta 'EN ISO 7010'



F001
Fire extinguisher



F002
Fire hose reel



F003
Fire ladder



F004
Collection of
firefighting equipment



F005
Fire alarm call point



F006
Fire emergency
telephone



M002
Refer to instruction
manual-booklet



M003
Wear ear protection



M004
Wear eye protection



M005
Connect an earth
terminal to the ground



M006
Disconnect mains plug
from electrical outlet



M007
Opaque eye
protection must be



M008
Wear safety footwear



M009
Wear protective
gloves



M010
Wear protective
clothing



M011
Wash your hands



M012
use handrail



M013
Wear a face shield



M014
Wear head protection



M015
Wera high-visibility
clothing



M016
Wear a mask



M017
Wear spiratory
protection



M018
Wear a safety harness



M019
Wear a welding mask



M020
Wear safety belts



M021
Disconnect before
carryng out



M022
Use barrier cream



M023
Use footbridge



M024
Use this walkway



M025
Protect infant's eyes
with opaque eye

Cartelli della raccolta 'EN ISO 7010'



M026
Use protective apron



P001
General prohibition sign



P002
No smoking



P003
No open flame; Fire,
open ignition source



P004
No thoroughfare



P005
Not drinking water



P006
No access for forklift
trucks and other



P007
No access for people
with active implanted



P008
No metallic articles or
watches



P010
Do not touch



P011
Do not extinguish with
water



P012
No heavy load



P013
No activated mobile
phones



P014
No access for people
with metallic implants



P015
No reaching in



P017
No pushing



P018 - No sitting



P019 - No stepping on
surface



P020
Do not use lift in the
event of fire



P021 - No dogs



P022
P022 - No eating or
drinking



P023
Do not obstruct



P024
Do not walk or stand
here



P025
Do not use this
incomplete scaffold



P026
Do not use this device
in a bathtub, shower



P027
Do not use this lift for
people



P028
Do not wear gloves



P029
No photography



P030
Do not tie knots in
rope



P031
Do not alter the state
of the switch

Cartelli della raccolta 'EN ISO 7010'



P032
Do not use for face grinding



P033
Do not use for wet grinding



P034
Do not use with hand-held grinding



W001
General warning sign



W002
Warning; explosive material



W003
Warning; Radioactive material or ionizing



W004
Warning; laser beam



W005
Warning; Non-ionizing radiation



W006
Warning; Magnetic field



W007
Warning; Floor-level obstacle



W008
Warning; Drop (fall)



W009
Warning; Biological hazard



W010
Warning; Low temperature-freezing



W011
Warning; Slipper surface



W012
Warning; Electricity



W013
Warning; Guard dog



W014
Warning; Forklift trucks and other



W015
Warning; Toxic material



W016
Warning; Toxic material



W017
Warning; Hot surface



W018
Warning; Automatic Start-up



W019
Warning; Crushing



W020
Warning; Overhead obstacle



W021
Warning; Flammable material



W022
Warning; Sharp element



W023
Warning; Corrosive substance



W024
Warning; Crushing of hands



W025
Warning; Counterrotating rollers



W026
Warning; Battery charging



W027
Warning; Optical radiation



W028
Warning; Oxidizing
substance



W029
Warning; Pressurized
cylinder